

Furnaces that Meet Federal TAX Credit Requirement
Updated B ROCKY, 09/14/09

COLEMAN	
Model	Fed Tax Credit Amount (% of Installed Cost)
CM8M080B12MP11	6%
CM8M080C16MP11	6%
CM8M100C16MP11	6%
CM8M100C20MP11	6%
CM8M120C20MP11	6%
CM9M060B12MP11	30%
CM9M080B12MP11	30%
CM9M080C16MP11	30%
CM9M100C16MP11	30%
CM9M100C20MP11	30%
CM9M120D20MP11	30%
CMLM080B12MP11	6%
CMLM080C16MP11	6%
CMLM100C16MP11	6%
CMLM100C20MP11	6%
CMLM120C20MP11	6%
CP8C060A12MP11	6%
CP8C080B12MP11	6%
CP8C080C16MP11	6%
CP8C100C16MP11	6%
CP8C100C20MP11	6%
CP8C120C20MP11	6%
CP9C060B12MP11	30%
CP9C060B12MP12	30%
CP9C080B12MP11	30%
CP9C080B12MP12	30%
CP9C080C16MP11	30%
CP9C080C16MP12	30%
CP9C100C16MP11	30%
CP9C100C16MP12	30%
CP9C100C20MP11	30%
CP9C100C20MP12	30%
CP9C120D20MP11	30%
CP9C120D20MP12	30%
CPLC060A12MP11	6%
CPLC060A12MP12	6%
CPLC080B12MP11	6%
CPLC080B12MP12	6%
CPLC080C16MP11	6%
CPLC080C16MP12	6%
CPLC100C16MP11	6%
CPLC100C16MP12	6%
CPLC100C20MP11	6%
CPLC100C20MP12	6%
CPLC120C20MP11	6%
CPLC120C20MP12	6%
FC8V100B16UH11	9%
FC8V100C16DH11	9%
FC8V100C16UH11	9%
FC8V100C20DH11	9%
FC8V100C20UH11	9%
FC8V120C20DH11	9%
FC8V120C20UH11	9%
FC9C060B12DH11	30%
FC9C060B12UP11	30%
FC9C080B12DH11	30%
FC9C080B12UP11	30%
FC9C080C16DH11	30%
FC9C080C16UP11	30%
FC9C100C16DH11	30%
FC9C100C16UP11	30%

COLEMAN	
Model	Fed Tax Credit Amount (% of Installed Cost)
FC9C100C20DH11	30%
FC9C100C20UP11	30%
FC9C120D20DH11	30%
FC9C120D20UP11	30%
FC9M060B12DH11	30%
FC9M060B12UP11	30%
FC9M080B12DH11	30%
FC9M080B12UP11	30%
FC9M080C16DH11	30%
FC9M080C16UP11	30%
FC9M100C16DH11	30%
FC9M100C16UP11	30%
FC9M100C20DH11	30%
FC9M100C20UP11	30%
FC9M120D20DH11	30%
FC9M120D20UP11	30%
FC9V040A12UP11	6%
FC9V060B12DH11	6%
FC9V060B12UP11	6%
FC9V060B12UP12	30%
FC9V080B12DH11	6%
FC9V080B12UP11	6%
FC9V080C16DH11	6%
FC9V080C16DH12	6%
FC9V080C16UP11	6%
FC9V080C16UP12	30%
FC9V100C20DH11	6%
FC9V100C20DH12	6%
FC9V100C20UP11	6%
FC9V100C20UP12	30%
FC9V120D20DH11	6%
FC9V120D20DH12	6%
FC9V120D20UP11	6%
FC9V120D20UP12	30%
GM9F048B12UP11	30%
GM9F064C16DH11	30%
GM9F064C16UP11	30%
GM9F080C16DH11	30%
GM9F080C16UP11	30%
GM9F096D20UP11	30%
GM9V040A12UP11	6%
GM9V060B12DH11	6%
GM9V060B12UP11	6%
GM9V060B12UP12	30%
GM9V080B12DH11	6%
GM9V080B12UP11	6%
GM9V080C16DH11	6%
GM9V080C16DH12	6%
GM9V080C16UP11	6%
GM9V080C16UP12	30%
GM9V100C20DH11	6%
GM9V100C20DH12	6%
GM9V100C20UP11	6%
GM9V100C20UP12	30%
GM9V120D20DH11	6%
GM9V120D20DH12	6%
GM9V120D20UP11	6%
GM9V120D20UP12	30%
LC8V100B16UH11	9%
LC8V100C16DH11	9%
LC8V100C16UH11	9%
LC8V100C20DH11	9%
LC8V100C20UH11	9%
LC8V120C20DH11	9%

COLEMAN	
Model	Fed Tax Credit Amount (% of Installed Cost)
LC8V120C20UH11	9%
MG9S060B12MP11	30%
MG9S080B12MP11	30%
MG9S080C16MP11	30%
MG9S100C16MP11	30%
MG9S100C20MP11	30%
MG9S120D20MP11	30%
TG9S040A08MP11	30%
TG9S060A10MP11	30%
TG9S060B12MP11	30%
TG9S080B12MP11	30%
TG9S080C16MP11	30%
TG9S080C22MP11	30%
TG9S100C16MP11	30%
TG9S100C20MP11	30%
TG9S120D16MP11	30%
TG9S120D20MP11	30%
TG9S130D20MP11	30%
TM8V060A12MP11	9%
TM8V080B12MP11	9%
TM8V080C16MP11	9%
TM8V100C16MP11	9%
TM8V100C20MP11	9%
TM8V120C20MP11	9%
TM8X060A12MP11	6%
TM8X080B12MP11	6%
TM8X080C16MP11	6%
TM8X100C16MP11	6%
TM8X100C20MP11	6%
TM8X120C20MP11	6%
TM9T060B12MP11	30%
TM9T080B12MP11	30%
TM9T080C16MP11	30%
TM9T100C16MP11	30%
TM9T100C20MP11	30%
TM9T120D20MP11	30%
TM9V060B12MP11	30%
TM9V080B12MP11	30%
TM9V080C16MP11	30%
TM9V100C16MP11	30%
TM9V100C20MP11	30%
TM9V120D20MP11	30%
TM9X060B12MP11	30%
TM9X080B12MP11	30%
TM9X080C16MP11	30%
TM9X100C16MP11	30%
TM9X100C20MP11	30%
TM9X120D20MP11	30%
TMLV060A12MP11	9%
TMLV080B12MP11	9%
TMLV080C16MP11	9%
TMLV100C16MP11	9%
TMLV100C20MP11	9%
TMLV120C20MP11	9%
TMLX060A12MP11	6%
TMLX080B12MP11	6%
TMLX080C16MP11	6%
TMLX100C16MP11	6%
TMLX100C20MP11	6%
TMLX120C20MP11	6%