

Furnaces that Meet Federal TAX Credit Requirement  
Updated B ROCKY, 09/14/09

YORK	
Model	Fed Tax Credit Amount (% of Installed Cost)
GM9V040A12UP11	6%
GM9V060B12DH11	6%
GM9V060B12UP11	6%
GM9V060B12UP12	30%
GM9V080B12DH11	6%
GM9V080B12UP11	6%
GM9V080C16DH11	6%
GM9V080C16DH12	6%
GM9V080C16UP11	6%
GM9V080C16UP12	30%
GM9V100C20DH11	6%
GM9V100C20DH12	6%
GM9V100C20UP11	6%
GM9V100C20UP12	30%
GM9V120D20DH11	6%
GM9V120D20DH12	6%
GM9V120D20UP11	6%
GM9V120D20UP12	30%
GY9F048B12UP11	30%
GY9F064C16DH11	30%
GY9F064C16UP11	30%
GY9F080C16DH11	30%
GY9F080C16UP11	30%
GY9F096D20UP11	30%
PC9B12N060DH11	30%
PC9B12N060UP11	30%
PC9B12N080DH11	30%
PC9B12N080UP11	30%
PC9C16N080DH11	30%
PC9C16N080UP11	30%
PC9C16N100DH11	30%
PC9C16N100UP11	30%
PC9C20N100DH11	30%
PC9C20N100UP11	30%
PC9D20N120DH11	30%
PC9D20N120UP11	30%
PM9B12N060DH11	30%
PM9B12N060UP11	30%
PM9B12N080DH11	30%
PM9B12N080UP11	30%
PM9C16N080DH11	30%
PM9C16N080UP11	30%
PM9C16N100DH11	30%
PM9C16N100UP11	30%
PM9C20N100DH11	30%
PM9C20N100UP11	30%
PM9D20N120DH11	30%
PM9D20N120UP11	30%
PV8B16L100UH11	9%
PV8B16N100UH11	9%
PV8C16L100DH11	9%
PV8C16L100UH11	9%
PV8C16N100DH11	9%
PV8C16N100UH11	9%
PV8C20L100DH11	9%
PV8C20L100UH11	9%
PV8C20L120DH11	9%
PV8C20L120UH11	9%
PV8C20N100DH11	9%
PV8C20N100UH11	9%
PV8C20N120DH11	9%

YORK	
Model	Fed Tax Credit Amount (% of Installed Cost)
PV8C20N120UH11	9%
PV9A12N040UP11	6%
PV9B12N060DH11	6%
PV9B12N060UP11	6%
PV9B12N060UP12	30%
PV9B12N080DH11	6%
PV9B12N080UP11	6%
PV9C16N080DH11	6%
PV9C16N080DH12	6%
PV9C16N080UP11	6%
PV9C16N080UP12	30%
PV9C20N100DH11	6%
PV9C20N100DH12	6%
PV9C20N100UP11	6%
PV9C20N100UP12	30%
PV9D20N120DH11	6%
PV9D20N120DH12	6%
PV9D20N120UP11	6%
PV9D20N120UP12	30%
TG9S040A08MP11	30%
TG9S060A10MP11	30%
TG9S060B12MP11	30%
TG9S080B12MP11	30%
TG9S080C16MP11	30%
TG9S080C22MP11	30%
TG9S100C16MP11	30%
TG9S100C20MP11	30%
TG9S120D16MP11	30%
TG9S120D20MP11	30%
TG9S130D20MP11	30%
TM8V060A12MP11	9%
TM8V080B12MP11	9%
TM8V080C16MP11	9%
TM8V100C16MP11	9%
TM8V100C20MP11	9%
TM8V120C20MP11	9%
TM8X060A12MP11	6%
TM8X080B12MP11	6%
TM8X080C16MP11	6%
TM8X100C16MP11	6%
TM8X100C20MP11	6%
TM8X120C20MP11	6%
TM9T060B12MP11	30%
TM9T080B12MP11	30%
TM9T080C16MP11	30%
TM9T100C16MP11	30%
TM9T100C20MP11	30%
TM9T120D20MP11	30%
TM9V060B12MP11	30%
TM9V080B12MP11	30%
TM9V080C16MP11	30%
TM9V100C16MP11	30%
TM9V100C20MP11	30%
TM9V120D20MP11	30%
TM9X060B12MP11	30%
TM9X080B12MP11	30%
TM9X080C16MP11	30%
TM9X100C16MP11	30%
TM9X100C20MP11	30%
TM9X120D20MP11	30%
TMLV060A12MP11	9%
TMLV080B12MP11	9%
TMLV080C16MP11	9%
TMLV100C16MP11	9%

YORK	
Model	Fed Tax Credit Amount (% of Installed Cost)
TMLV100C20MP11	9%
TMLV120C20MP11	9%
TMLX060A12MP11	6%
TMLX080B12MP11	6%
TMLX080C16MP11	6%
TMLX100C16MP11	6%
TMLX100C20MP11	6%
TMLX120C20MP11	6%
YM8M080B12MP11	6%
YM8M080C16MP11	6%
YM8M100C16MP11	6%
YM8M100C20MP11	6%
YM8M120C20MP11	6%
YM9M060B12MP11	30%
YM9M080B12MP11	30%
YM9M080C16MP11	30%
YM9M100C16MP11	30%
YM9M100C20MP11	30%
YM9M120D20MP11	30%
YMLM080B12MP11	6%
YMLM080C16MP11	6%
YMLM100C16MP11	6%
YMLM100C20MP11	6%
YMLM120C20MP11	6%
YP8C060A12MP11	6%
YP8C080B12MP11	6%
YP8C080C16MP11	6%
YP8C100C16MP11	6%
YP8C100C20MP11	6%
YP8C120C20MP11	6%
YP9C060B12MP11	30%
YP9C060B12MP12	30%
YP9C080B12MP11	30%
YP9C080B12MP12	30%
YP9C080C16MP11	30%
YP9C080C16MP12	30%
YP9C100C16MP11	30%
YP9C100C16MP12	30%
YP9C100C20MP11	30%
YP9C100C20MP12	30%
YP9C120D20MP11	30%
YP9C120D20MP12	30%
YPLC060A12MP11	6%
YPLC060A12MP12	6%
YPLC080B12MP11	6%
YPLC080B12MP12	6%
YPLC080C16MP11	6%
YPLC080C16MP12	6%
YPLC100C16MP11	6%
YPLC100C16MP12	6%
YPLC100C20MP11	6%
YPLC100C20MP12	6%
YPLC120C20MP11	6%
YPLC120C20MP12	6%